

**To Reboot:**

**QWL 3.0:** Click the reset button, the lower right side of the face.

**Max Case:** Click the power button, located on the right side of the face.

**Reg Case:** Click the power button, the blue light located on left side of face.

**Wait for 3 minutes and the qd2040 should be restarted.**

**\*\*\*Note: Some of the motherboards make a beep to indicate a restart, also fans are a good indication.**

**To Shutdown:**

**QWL 3.0:** Press and hold the reset button for 10 seconds.


**Max Case:** Press and hold the power button for 10 seconds, the POWER LED will go out.

**Reg Case:** Press and hold the power button for 10 seconds.

**QWL 3.0 Reset Button**



**Max Case Power Button**



**Reg Case Power Button**



**To Power Off (not recommended):**

- Remove the barrel connector (power adapter) from the QD2040 for 5 seconds.
- Do not unplug the brick from the wall, it is not the same as unplugging the barrel connector.
- Please note: This method may corrupt the hard drive.

