

Wiring Connections for PX1060/SZ2182

Overview

The PX1060 is a remote temperature sensor for use with US5182, SZ2182, and SZ1025b. When using with the SZ2182, you must use a QE82 Setpoint Adaptor to complete the circuit. Follow the diagram below.

